LABORATORY SERVICES REPORT

Report Number: N1091141.0001 Service Date:

07/14/11

Report Date: 10/24/11 Revision 1 - Add 56-day Results

611 Lunken Park Dr. Cincinnati, OH 45226

513-321-5816

Client

Attn: James Sist

7771 Woodstone Drive Ste 100

Chemtec International, Inc.

Cincinnati, OH 45244

Project

ChemTec One - Testing/Consulting

611 Lunken Park Drive

Cincnnati, OH

Project Number: N1091141

Submitted herewith are the results of the one absorption test conducted with ChemTec One, a reactive silicate, having been previously applied in accordance with manufacturer's specifications. The absorption test procedures were conducted in general accordance with ASTM C 642. The test specimen was a normal weight, air entrained concrete mix that was immersed in water and maintained in the HCN laboratory for the time periods indicated below.

Absorption Result:

Specimen #1: 0.18% after 48 hours

Specimen #1: 0.49% after 56 days

Services:

Terracon Rep.: Jason A. Sander, P.E.

Reported To: Contractor:

Report Distribution:

Reviewed By:

Jason A. Sander, P.E.

The tests were performed in general accordance with applicable ASTM, AASHTO, or DOT test methods. This report is exclusively for the use of the client indicated above and shall not be reproduced except in full without the written consent of our company. Test results transmitted herein are only applicable to the actual samples tested at the location(s) referenced and are not necessarily indicative of the properties of other apparently similar or identical materials. CT0001, 9-28-10, Rev.8 Page 1 of 1